

FIGURE 1B




FIGURE 2




FIGURE 3A




FIGURE 3B




FIGURE 3C

6/13




FIGURE 3D

7/13




FIGURE 4




FIGURE 5




FIGURE 6

TITLE: SHOCK EVENT ERROR LOGGING IN A DISK DRIVE INVENTOR: Raffi Codilian APPLICATION NUMBER: 10/008,763




FIGURE 7




FIGURE 8




FIGURE 9B





FIGURE 9C



TITLE: SHOCK EVENT ERROR LOGGING IN A DISK DRIVE INVENTOR: Raffi Codilian APPLICATION NUMBER: 10/008,763

13/13




FIGURE 9E